



Christian County Commission

100 West Church St, Room 100
Ozark, MO 65721

<http://ChristianCountyMO.iqm2.com>

July Term

~ Minutes ~

Friday, July 10, 2015

9:00 AM

The Christian County Courthouse

I. Convene

The meeting was called to order at 9:00 AM by Presiding Commissioner Ray Weter

Attendee Name	Title	Status	Arrived
Ray Weter	Presiding Commissioner	Present	8:15 AM
Bill Barnett	Western Commissioner	Absent	
Sue Ann Childers	Eastern Commissioner	Present	8:15 AM
Mary Argiso	Assistant	Present	8:15 AM

II. Agenda

Motion/Vote - 8:15 AM Miranda Beadles-Highway Administrator

Discussion - Emergency Meeting-Discussion Flooding and Damage of County Roads

The meeting was attended by C I Supervisor Richard Teague.

The Commission met for an emergency session due to the recent flooding.

FEMA, SEMA, Commissioner Weter, Commissioner Childers, CI Supervisor Richard Taegue, Ms. Linda Barger EM Dept., and Headliner News Reporter Amber Duran, will meet at 9:00 a.m. today at the Emergency Management office to discuss and inspect flood damage locations.


Commissioner Weter entertained a motion to observe infrastructure damage due to recent flooding.

RESULT:	ADOPTED [UNANIMOUS]
MOVER:	Sue Ann Childers, Eastern Commissioner
SECONDER:	Ray Weter, Presiding Commissioner
AYES:	Ray Weter, Sue Ann Childers
ABSENT:	Bill Barnett

III. Adjournment

The meeting was closed at 5:00 PM

Road damage inspection ended at 5:00 p.m.


Ray Weter

Presiding Commissioner, Ray Weter


Bill Barnett

Western Commissioner, Bill Barnett


Sue Ann Childers

Eastern Commissioner, Sue Ann Childers

2015 Damaged Road List/ FEMA

1. Keltner Road- total washout.(Lost about 30 foot of slab)
2. Parchcorn Road –Major washout/ loss of road sections and loss of bridge/ loss of base rock/large culverts.(washed out twice in two weeks).
3. Blue Creek Road-loss of road section/loss of Base rock
4. DAY Lane-Loss of base rock.
5. Swan Cave Road-Edge work needed/loss chip next to slab
6. Fairview-Debris on slab loss of base rock.
7. Oldfield Road –loss of base rock
8. Peck Road-Debris on road /in ditch/on slab/loss of base rock.
9. Anchor hills Road-Road section/ loss of rip rap/loss of asphalt/remove debris for road and ditch.
10. Arapaho-Road section loss/loss of base rock/ ditch line needs reestablished and culverts need cleaned out/intersection with Ballard road washed out. Debris on road.
11. Temple hill- loss of base rock.
12. Lassley road- section loss/ loss of base stone
13. Martins branch- loss of base stone
14. Braden road- debris on road and bridge/ wash out next to slab/ loss of base stone
15. Ballard hill washed out/ loss of some base stone/ road flooded/ excess gravel to be removed/culvert damaged
16. Johnsford Hill washed out/ditches full/loss of base rock
17. Patterson road – loss of base rock/small section loss
18. Sawmill- washed out near dead end multiple times
19. Alpine road- wash out/ loss of base rock
20. Smith Road- Loss of base rock/ small wash outs
21. Hummingbird Road- loss of base rock on hill/ reestablished ditch line
22. Pinoak road- washed off base rock
23. Cedar creek- wash outs/ loss of base rock/ clean ditches

24. Parchcorn and HWY 125 intersection – loss of asphalt/ needs milling and overlay
25. Horner road- loss of asphalt/ loss of shot rock-rip rap/ culvert inadequate/ clean and reestablish ditch line
26. Cottonwood and Symrna intersection- wash out at end of bridge/ pavement buckled in intersection/ mill out and relay
27. Homestead and HWY 125 intersection- clean and reestablish ditch line/ loss of pavement/ mill and relay
28. Rosmead- clean and reestablish ditch line/ replace rip rap/ fix wash outs
29. Arbour- edge work/
30. Borneman- wash out next to water crossin/ loss of pavement/ need rip rap
31. Buckeye- fix ditch/ loss of chip and seal next to slab
32. Johnson Road- repair culvert/ repair pavement over culvert/ loss of pavement next to slab/ milling and overlay required.
33. Red bridge- small section loss/ base rock loss/ clean debris off slab
34. Center road- east end hill washed/ loss of base rock
35. Debbie lane- undercut concrete slab must repair

Many small areas of edge work on many county roads